AMENDMENT OF SOLICITAT	TION/MODIFICAT	TON OF CONTRACT	1. CONTRA	ACT ID CODE	PAGE O	F PAGES
				0	1	3
2. AMENDMENT/MODIFICATION NO. P00008	3. EFFECTIVE DATE 13-Feb-2002	4. REQUISITION/PURCHASE RE	Q. NO.	5. PROJECT	NO.(If appli	cable)
6. ISSUED BY COD. AETC CONS 82 CONS/LGCK 2021 FIRST STREET WEST	E FA3002	7. ADMINISTERED BY (If other to 82 CONS/LGC (LINDA LITTLI LINDA.LITTLE@SHEPPARD. 136 K AVENUE, SUITE 1	E, CONTŔA	CODE CTING OFFIC	FA3020 ER)	
RANDOLPH AFB, TX 78150-4302		SHEPPARD AFB, TX 76311-	2746			
8. NAME AND ADDRESS OF CONTRACTOR (No.	, Street, County, State and Z	Cip Code)	9A. AMENI	DMENT OF SC	DLICITATIO	ON NO.
LEAR SIEGLER SERVICES, INC 175 ADMIRAL COCHRANE DRIVE			9B. DATED	(SEE ITEM 1	1)	
TO ABMILLE GOOTHAND BRIVE		X	10A. MOD. F41689-01	OF CONTRAC -C-0029	CT/ORDER	NO.
ANNAPOLIS, MD 21401			10B. DATE	D (SEE ITEM		
CODE 08MB5	FACILITY CODE	X X X X X X X X X X X X X X X X X X X	11-Oct-200	01		
The above numbered solicitation is amended as set forth in Its		TO AMENDMENTS OF SOLICITA	is extended,	is not ext		
Offers must acknowledge receipt of this amendment prior to (a) By completing Items 8 and 15, and returning or (c) By separate letter or telegram which includes a reference RECEIVED AT THE PLACE DESIGNATED FOR THE RE REJECTION OF YOUR OFFER. If by virtue of this amenda provided each telegram or letter makes reference to the solici 12. ACCOUNTING AND APPROPRIATION DATA	copies of the document; (b) By ac ce to the solicitation and amendment CEIPT OF OFFERS PRIOR TO Toment you desire to change an offer tation and this amendment, and is	knowledging receipt of this amendment on eac ent numbers. FAILURE OF YOUR ACKNOW THE HOUR AND DATE SPECIFIED MAY R already submitted, such change may be made	h copy of the of LEDGMENT T ESULT IN THE by telegram or l	го ве Е		
13 THIS ITEM	APPLIES ONLY TO MOD	DIFICATIONS OF CONTRACTS/ORI)FRS			
IT MODIFI	ES THE CONTRACT/ORD	ER NO. AS DESCRIBED IN ITEM 1	4.			
A.THIS CHANGE ORDER IS ISSUED PURSUAN CONTRACT ORDER NO. IN ITEM 10A.	TT TO: (Specify authority)	THE CHANGES SET FORTH IN ITE	M 14 ARE N	MADE IN THE		
B.THE ABOVE NUMBERED CONTRACT/ORDE office, appropriation date, etc.) SET FORTH IN				as changes in p	aying	
C.THIS SUPPLEMENTAL AGREEMENT IS ENT I-547 FAR 52.243-1, Changes-Fixed Price, Alt		TO AUTHORITY OF:				
D.OTHER (Specify type of modification and author						
E. IMPORTANT: Contractor is not, X	is required to sign this do	ocument and return 1 cop	oies to the iss	uing office.		
DESCRIPTION OF AMENDMENT/MODIFICAT where feasible.) To revise Page 6 of the Bid Schedule and the Page 6 of the Bid Schedule and the Page 6 of the Bid Schedule And Page 6 of the			contract subje	ect matter		
Except as provided herein, all terms and conditions of the documents. 15A. NAME AND TITLE OF SIGNER (Type or print).		as heretofore changed, remains unchanged and 5A. NAME AND TITLE OF CONTRA			print)	
						HONES
15B. CONTRACTOR/OFFEROR 1		6B. UNITED STATES OF AMERICA			6C. DATE S	IGNED
(Signature of person authorized to sign)	<u>B</u>	(Signature of Contracting Officer)				

CONTINUATION SHEET REFERENCE NO. OF DOCUMENT BEING CONTINUED PAGE F41689-01-C-0029-P00008 2 OF 3

NAME OF OFFEROR OR CONTRACTOR LEAR SIEGLER SERVICES, INC

SECTION SF 30 BLOCK 14 CONTINUATION PAGE

SUMMARY OF CHANGES

CAGE CODE: 08MB5 DUNS: 073871048 TIN: 52-1605019

- 14A. The purpose of this modification is to change Schedule B, Page 6, and make changes to the Statement of Work (SOW). This bilateral modification makes the following changes to the contract.
 - (1) Schedule B, Page 6 of 67, is being revised to add the SUB-CLINS on CLIN 0003 and CLIN 0008.
- (2) SOW, Table of Contents, Page ii, is being revised to add Appendix 3FG, Government-Furnished Land Mobile Radios, which consists of two pages.
- (3) SOW, Page 2-3-8 is being revised as follows: in paragraph 2.3.2.8 change the reference from paragraph 3.1.21.4 to read 3.1.22.4; paragraphs 2.3.2.9, 2.3.2.10, and 2.3.2.11 changes the reference for LMR equipment from Appendix 3FD to Appendix 3FG.
- (4) SOW, Page 2-4-3 is being revised as follows: at the end of paragraph 2.4.5.10 delete the phrase "on-time implementation." In paragraph 2.4.11, the reference is being change from paragraph 3.1.32.2 to read 3.1.33.2.
- (5) SOW, Page 3-1-27, paragraph 3.1.33.2 is being revised as follows: In 5th sentence delete "(ref Section 3B)." Fifth sentence from the end beginning with "Appendix 2B contains a map..." delete the entire sentence.
- (6) SOW, Appendix 3A, Page 3A-3, Change the date of AFI 36-2201 from "Apr 97" to "Apr 00" and change the AFI from "M" to "A".
- (7) SOW, Appendix 3FE, Page 3FE-1, delete "Warehouse Tug, AT-38" in replacement period FY02 (Number 86E870). On Page 3FE-2, add two new tugs at the end of the table (Numbers 01E321 and 01E323).

INSERT

- (8) SOW Add Appendix 3FG, Government-Furnished Land Mobile Radios (2 pages).
- 14B. Remove and insert the following pages:

REMOVE

Page 6 of 67 (P00005)	Page 7 of 67 (P00008)
Page ii	Page ii (P00008)
Page 2-3-8	Page 2-3-9 (P00008)
Page 2-4-3	Page 2-4-3 (P00008)
Page 3-1-27	Page 3-1-27 (P00008)
Page 3A-3	Page 3A-3 (P00008)
Page 3FE-1	Page 3FE-1 (P00008)
Page 3FE-2	Page 3FE-2 (P00008)
	Page 3FG-1 (P00008)
	Page 3FG-2 (P00008)

CONTINUATION SHEET REFERENCE NO. OF DOCUMENT BEING CONTINUED PAGE F41689-01-C-0029-P00008 3 OF 3

NAME OF OFFEROR OR CONTRACTOR LEAR SIEGLER SERVICES, INC

14C. No other changes are made to the terms and conditions of the contract.

Changes in Section G

Summary for the Payment Office

Total funded amount of the current fiscal year remains at \$26,545,151.51.

Total contract amount remains at \$26,739,390.89.

TABLE OF CONTENTS

TITLE	PAGE	TOTAL PAGES
1. MISSIONS	1-1-1	1
2. APPLICABLE TO ALL SERVICES Statement of Work Summary of Expectations Service Delivery Summary		
Government-Furnished Property (GFP) and Services General Information	2-4-1	2-3-1 6
Appendices Publications	2A-1	4
3. AIRCRAFT MAINTENANCE AT SHEPPARD AFB Statement of Work		
Description of Services Service Delivery Summary	3-1-1 3-2-1	61 3
Government-Furnished Property (GFP) and Services General Information	3-3-1	1
Appendices		
Publications	3A-1	6
Workload Estimates	3B-1	22
T-37 Flying Hour Workload Data	3BA-1	21
T-38 Flying Hour Workload Data	3BB-1	35
AT-38B Flying Hour Workload Data	3BC-1	17
Maps and Work Area Layout	3C-1	49
Required Reports	3D-1	3
Collateral Tasks (Additional Duties)	3E-1	3
Government-Furnished Property (Facilities)	3F-1	1
Government-Furnished Property (EAID)	3FA-1	22
Government-Furnished Property (NONEAID)	3FB-1	98
Government-Furnished Property (Common Hand		
Tools and Special Tools)	3FC-1	1062
Government-Furnished Property (ADPE)	3FD-1	9
Government-Furnished Property (Vehicles)	3FE-1	2
Government-Furnished Training	3FF-1	2
Government-Furnished Land Mobile Radios	3FG-1	2
OPLANS (Tasked Agency)	3G-1	1
Support Agreements	3H-1	1
Special Training, Certification, or License Requirement	3I-1	1

TOTAL PAGES: 1,477

ordered procured through base supply). On-call maintenance service will be available 0700-1630, Monday through Friday, excluding Federal holidays and the 80th FTW down days. There will be no cost to the contractor for this service unless the contractor's usage exceeds the authorized production limits as provided to the contractor's copier monitors in writing by the Base Copier Manager. The Government reserves the right to charge the contractor for copies exceeding established production limitations. All usage of the Government provided copiers by the contractor will be for official Government use only.

- 2.3.2.5. Refuse Collection. The Government will provide garbage, trash and refuse pickup and disposal service from outdoor refuse containers.
- 2.3.2.6. The Government will provide temporary storage facilities for hazardous chemicals and waste generated and accumulated by the contractor in the course of the maintenance activities required by this SOW. The contractor shall be responsible to maintain these facilities in accordance with custodial requirements, fire, safety and security.
- 2.3.2.7. Insect and Rodent Control. The Government will furnish insect and rodent control for contractor-utilized Government-provided facilities, to control only pests that have the potential to spread disease or inflict injury to building occupants. The Government will control the following pests: ants, roaches, bees, wasps, hornets, fleas, ticks and rats. If any of the above listed pests become a serious infestation, Government will provide required pest control services to eliminate the pests. After the pest is controlled, it will be the occupant's responsibility to maintain their facility pest free.
- 2.3.2.8. Grounds Maintenance. The Government will provide grounds maintenance, except as noted in paragraph 3.1.22.4.
- 2.3.2.9. Equipment Maintenance. Maintenance of equipment, except AGE in Appendices 3FA and 3FB, which is beyond user maintenance, as verified by Government QA Personnel, will be furnished by the Government. Maintenance of Land Mobile Radio (LMR) System as listed in Appendix 3FG will be as specified in paragraph 2.3.2.10.
- 2.3.2.10. The Government will furnish LMR equipment to the minimum extent necessary for mission accomplishment. (Appendix 3FG will be used to list Government furnished LMR equipment.)
- 2.3.2.11. LMR maintenance support will be provided by contract with radio maintenance vendors for LMR equipment as listed in Appendix 3FG. The contractor shall not attempt to repair Government-furnished LMR equipment. The contractor shall provide an individual to perform the duties of LMR Net Manager for nets under their control IAW AFI 33-106. (See Appendix 3A)

SHEPPARD AFB AIRCRAFT MAINTENANCE

- 2.4.5.10. The contractor shall use procedures contained in AFMAN 23-110, Volume 2, Part 2, Chapter 22, for assigning, accounting, reporting, and disposition of Government-owned vehicles.
- 2.4.5.11. The contractor shall participate in each unit's Top Wheels Competition IAW AETCI 24-301 paragraphs 3, 5.5, 6.1, and 9 through 9.3.2.
- 2.4.6. Contractor shall provide all user maintenance for the care and/or upkeep of all Government-furnished office equipment except those as listed in Appendix 3FD.
- 2.4.7. Contractor shall provide a non-Government telephone service through off-base switching equipment for conducting personal or unofficial business.
- 2.4.8. Contractor shall provide annual recurring egress/cockpit familiarization training to Government QA Personnel.
- 2.4.9. Contractor shall provide CPR, blood pathogen and first aid training IAW OSHA standards.
- 2.4.10. Distinctive Clothing. As specified in this Statement of Work.
- 2.4.11. Off Station Support. See Section 3-1, paragraph 3.1.33.2.
- 2.4.12. Personal Protective Equipment. Contractor shall provide all required personal protective equipment, i.e., respirators, hearing protection, eye protection, gloves, safety shoes, etc. IAW OSHA standards.
- 2.4.13. Contractor shall conduct a Job Safety Analysis (JSA) for each work center to determine the need for protective clothing IAW AFI 91-202 and OSHA standards not later than responsibility assumption dates. The JSA shall be filed in each applicable work center.
- 2.4.14. Publications. Publications that apply to the SOW are listed in Appendix 2A and 3A. The publications have been coded as mandatory or advisory. The contractor is obligated to follow those publications and use those forms coded as mandatory to the extent specified in other sections of this SOW. Contractor shall be guided by those publications or use those forms coded advisory to the extent necessary to accomplish requirements in this SOW. The Government will provide all publications and forms listed at the start of the contract.
 - 2.4.14.1. Where the contractor is permitted to use Air Force and other Government publications or directives as an advisory guide (in Appendix 2A and 3A) rather than for mandatory compliance in the performance of this contract, the contractor may deviate from the directive using the following procedures.

- 3.1.33.2. Off-Station Aircraft Support. Aircraft which become NMC while off station, other than an Air Force base that has the capability to make the needed repairs, and within a 300 mile radius, shall be supported by the owning unit. Support for aircraft beyond the 300 mile radius will be the responsibility of the closest base possessing like aircraft. This may include non-AETC aircraft that the contractor has the capability to support as determined by the CO. Distance shall be determined by using the Rand McNally Standard Highway Mileage Guide. A copy of this guide will be furnished to the contractor and maintained in the Maintenance Operation Center for this purpose. Contractor shall initiate support action upon notification, by the owning organization, that an AF, AETC, or interservice aircraft is NMC offstation, and a determination has been made that Sheppard AFB is the closest Contractor shall dispatch required maintenance crews, supplies, technical orders and support equipment not later than the next normal duty day following notification. Under circumstances where multiple aircraft require off-station support by a single base, priorities will be negotiated between the owning base(s) and the supporting base to minimize negative mission impacts. However, as a minimum, when multiple AF, AETC or interservice NMC off-station aircraft are within 300 miles of Sheppard AFB, maintenance crews shall be dispatched and shall have begun performing required maintenance on the aircraft not later than the beginning of the third duty day following notification. For each additional 400 miles, or portions thereof, an additional travel day will be allowed. Contractor shall provide continuous support necessary, to include weekends, to return the aircraft to mission capable (MC) status. Because Sheppard AFB will be the last AETC Unit with the T-37 aircraft, off-station recovery could include almost any location in North America until the T-37 leaves the DoD inventory.
 - 3.1.33.2.1. The contractor shall perform BPO, thruflight and preflight inspections on off-station T-37, T-38 and T-6A aircraft as part of the off-station maintenance support/recovery.
 - 3.1.33.2.2. The contractor may utilize Government air transportation for Mission Essential Ground Personnel (MEGP) in support of off-station, non-mission capable, aircraft, when space is available IAW AFI 11-401. MEGP flight scheduling will be coordinated and approved by the FC and CO.
 - 3.1.33.2.3. When using military, commercial or private transportation sources, the contractor and its employee(s) agree to indemnify and hold the United States and its employees harmless, whether in tort or in contract, for any and all loss or disability for injury to or death of

AFI 36-2201	Developing, Conducting and Managing Training	Apr 00	A
AFI 36-2211	Aircrew Qualification and Training	Dec 96	M
AFI 36-2217	Munitions Requirements for Aircrew Training	Jan 94	M
AFI 36-2863	History Awards	Jan 98	M
AFI 36-2903	Dress and Personal Appearance of AF Personnel	Jun 98	M
AFI 37-160,	The Air Force Publications and Forms Management	Nov 93	M
Vol. 7	Programs - Publication Libraries and Sets		
AFI 38-401	The Air Force Innovative Development through	Oct 97	M
	Employee Awareness (IDEA) Program		
AFI 40-201	Managing Radioactive Materials in the Air Force	Sep 00	M
AFI 63-124	Performance-Based Service (PBS) Contracts	Apr 99	A
AFI 64-117	Air Force Government-wide Purchase Card Program	Oct 00	A
AFI 91-202	The USAF Mishap Prevention Program	Aug 98	M
AFI 91-204	Safety Investigation and Reports	Nov 99	M

Air Force Mission Directives/Manuals/Pamphlets and DoD Directives.

NUMBER	TITLE	DATE	Mandatory/
			<u>Advisory</u>
AFCSM 21-556,	Core Automated Maintenance Systems (CAMS)	Nov 96	M
Vol. 1	Operator Manual		
AFCSM 21-556,	Introduction to CAMS Software Use Manual	Apr 97	M
Vol. 2			
AFCSM 21-558,	CAMS Comprehensive Engine Management	Jan 97	M
Vol. 2	System User Manual		
AFCSM 21-559,	CAMS Automatic Equipment Reporting	Nov 96	M
Vol. 2	Systems User Manual		
AFCSM 21-561,	CAMS Maintenance Events User Manual	Jan 97	M
Vol. 2			
AFCSM 21-563,	CAMS Job Data Documentation User Manual	Nov 96	M
Vol. 2			
AFCSM 21-564,	CAMS Status and Inventory Reporting User	Nov 96	M
Vol. 2	Manual		
AFCSM 21-565,	CAMS Operation Event Subsystem User Manual	Jan 97	M
Vol. 2			
AFCSM 21-566,	CAMS Inspection and Time Change User	Dec 96	M
Vol. 2	Manual		
AFCSM 21-567,	CAMS Equipment/Personnel Transfer User	Dec 96	M
Vol. 2	Manual		
AFCSM 21-568,	CAMS Time Compliance Technical Order User	Jan 97	M
Vol. 2	Manual		
AFCSM 21-569,	CAMS Personnel Management User Manual	Oct 96	M
Vol. 2			

0003	AWARD FEE POOL (6% of Total Target Costs) (Total Potential Award Fee Available for four (4) Quarterly Evaluation Periods is 6% of Target Costs (25% of Total Award Fee is available for each quarterly evaluation period to be funded quarterly by ACO modification as determined by the FDO.)) (IAW Clause B-3 and Award Fee Plan)		\$1,512,005.34	
OOO3AA	T-37 Award Fee			\$174,712.22
OOO3AB	T-38 Award Fee			\$175,354.82
OO03AC	AT-38B Award Fee			\$27,934.30
0004	HOURLY ADJUSTMENT RATE (IAW Clause B-9)			
	T-37 HOURLY ADJUSTMENT RATE T-38 HOURLY ADJUSTMENT RATE AT-38B HOURLY ADJUSTMENT RATE		\$107.65 \$152.83 \$245.00	
0005	TAI ADJUSTMENT RATE (IAW Clause B-12)			
	T-37 TAI ADJUSTMENT RATE T-38 TAI ADJUSTMENT RATE AT-38B TAI ADJUSTMENT RATE		\$271.28 \$534.91 \$477.75	
0006	RESERVED			
THE FOLL	OWING CONTRACT LINE ITEM IS FIRM FIXED PRICE	ED (NON-TAR	GET)	
0007	CONTRACTOR ACQUIRED VEHICLES (CAV) (IAW SOW para 2.4.4. And 2.4.5.)			\$141,306.39
THE FOLL	OWING CONTRACT LINE ITEMS ARE NOT-TO-EXCE	ED (NTE) (NC	N-TARGET)	
0008	WEEKEND/HOLIDAY FLYING	NTE	\$70,000.00	I

	(IAW SOW para 3.1.57.4.2 and Clause B-10) (This item will be funded by the ACO as required)	
AA8OOO	T-37 Weekend/Holiday Flying	\$32,354.00
OOO8AB	T-38 Weekend/Holiday Flying	\$32,473.00
OO08AC	AT-38 Weekend/Holiday Flying	\$5,173.00

OOO9 RESERVED

APPENDIX 3FE GOVERNMENT-FURNISHED PROPERTY AIRCRAFT MAINTENANCE SPECIAL PURPOSE VEHICLES

80 FTW SHEPPARD AFB

TYPE VEHICLE	WORK CENTER	USE	REPLACEMENT
			PERIOD (FY)
Warehouse Tug	T-38 A/R	Towing aircraft	FY02
		and AGE	82E241
Forklift	Hazardous Waste	Moving	FY02
		Hazardous waste	86E216
		barrels	
Tractor Support (Bobtail)	Engine Test Cell	Towing engines	FY02
		and AGE	86C566
Warehouse Tug	T-37 A/R	Towing aircraft	FY02
		and AGE	90E280
Tractor Support (Bobtail)	AGE	Towing AGE	FY03
			90C201
Tractor Support (Bobtail)	AGE	Towing AGE	FY03
			90C1020
Tractor Support (Bobtail)	AGE	Towing AGE	FY03
			90C679
Warehouse Tug	Tow Team (MOC)	Towing aircraft	FY03
	, ,	and AGE	91E980
Warehouse Tug	AT-38 (Flight Line)	Towing aircraft	FY03
		and AGE	91E981
Warehouse Tug	Tow Team (MOC)	Towing aircraft	FY04
	, ,	and AGE	92E1403
Warehouse Tug	Transient Alert	Towing aircraft	FY04
		and AGE	92E1408
Aircraft Boarding Stairs	Transient Alert	Boarding Aircraft	FY04
Warehouse Tug	T-38 (Flight Line)	Towing aircraft	FY08
		and AGE	96E09
Warehouse Tug	Flight Line Support	Towing aircraft	FY08
	(Engines)	and AGE	96E010
Warehouse Tug	Flight Line Support	Towing aircraft	No replacement
	(Engines)	and AGE	needed this
			contract.
			00E300
Warehouse Tug	T-38 PE	Towing aircraft	No replacement
		and AGE	needed this
			contract.
			00E297

SHEPPARD AFB AIRCRAFT MAINTENANCE

Warehouse Tug	T-37 A/R	Towing aircraft and AGE	No replacement needed this contract. 00E298
Warehouse Tug	T-37 (Flight Line)	Towing aircraft and AGE	No replacement needed this contract. 00E299
Warehouse Tug	T-38 (Flight Line)	Towing aircraft and AGE	No replacement needed this contract. 00E296
MB4 Tug	Transient Alert	Towing aircraft	Always Government- Provided 99L371
Warehouse Tug	Tow Team (MOC)	Towing aircraft and AGE	No replacement needed this contract. 01E321
Warehouse Tug	Tow Team (MOC)	Towing aircraft and AGE	No replacement needed this contract. 01E323

APPENDIX 3 FG GOVERNMENT-FURNISHED LAND MOBILE RADIOS

LAND N	MOBILE RADIO I	NVENTORY	00121414111	INT-FURNISHE		122 10 151
Status	Serial Number	Manufacturer	Model Number	Model Name	Equip Type	Sel Call
NEW	326AAS2764	MOTOROLA	H09RDC9PW5AN	XTS 3000-1	RAD, PORT	700545
NEW	326AAS2790	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700541
NEW	326AAS2793	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700529
NEW	326AAS2803	MOTOROLA	H09RDC9PW5AN	XTS 3000-1	RAD, PORT	700523
NEW	326AAW1869	MOTOROLA	H09RDC9PW5AN	XTS 3000-1	RAD, PORT	700530
NEW	326AAW1875	MOTOROLA	H09RDC9PW5AN	XTS 3000-1	RAD, PORT	700532
NEW	326AAW1876	MOTOROLA	H09RDC9PW5AN	XTS 3000-1	RAD, PORT	700539
NEW	326AAW1878	MOTOROLA	H09RDC9PW5AN	XTS 3000-1	RAD, PORT	700527
NEW	326AAW1879	MOTOROLA	H09RDC9PW5AN	XTS 3000-1	RAD, PORT	700546
NEW	326AAW1882	MOTOROLA	H09RDC9PW5AN	XTS 3000-1	RAD, PORT	700525
NEW	326AAW1916	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700531
NEW	326AAW1998	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700512
NEW	326AAW2349	MOTOROLA	H09RDH9PW7BN	XTS 3000-3	RAD, PORT	700528
NEW	326ABL1333	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700515
NEW	326ABL1334	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700519
NEW	326ABL1338	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700520
NEW	326ABL1339	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700517
NEW	326ABL1341	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700514
NEW	326ABL1344	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700518
NEW	326ABL1345	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700521
NEW	326ABL1347	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700522
NEW	326ABL1351	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700513
NEW	326ABL1352	MOTOROLA	H09RDC9PW5BN	XTS 3000-1	RAD, PORT	700516
NEW	326ABL1389	MOTOROLA	H09RDH9PW7BN	XTS 3000-3	RAD, PORT	700540
NEW	326ABL1395	MOTOROLA	H09RDH9PW7BN	XTS 3000-3	RAD, PORT	700535
NEW	326ABL1412	MOTOROLA	H09RDH9PW7BN	XTS 3000-3	RAD, PORT	700544
NEW	326ABL1414	MOTOROLA	H09RDH9PW7BN	XTS 3000-3	RAD, PORT	700547
NEW	326ABL1416	MOTOROLA	H09RDH9PW7BN	XTS 3000-3	RAD, PORT	700548
NEW	494AAW0435	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700580
NEW	494AAW0439	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700560
NEW	494AAW0441	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700567
NEW	494AAW0442	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700566
NEW	494AAW0444	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700568
NEW	494AAW0452	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700561
NEW	494AAW0455	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700558

APPENDIX 3 FG GOVERNMENT-FURNISHED LAND MOBILE RADIOS

NEW 494AAW0461 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700573 NEW 494AAW0467 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700565 NEW 494AAW0467 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700572 NEW 494AAW0468 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700578 NEW 494AAW0491 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700569 NEW 494AAW0493 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700582 NEW 494AAW0496 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700584 NEW 494AAW0505 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700574 NEW 494AAW0506 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700585 NEW 494AAW0506 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0501				0012:::::::	LIVI I OIKIVIOIIL		TILL I () (DI
NEW 494AAW0467 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700572 NEW 494AAW0468 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700578 NEW 494AAW0478 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700575 NEW 494AAW0491 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700569 NEW 494AAW0493 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700582 NEW 494AAW0495 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700582 NEW 494AAW0496 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700574 NEW 494AAW0505 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700585 NEW 494AAW0506 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700577 NEW 494AAW0511 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700577 NEW 494AAW0514	NEW	494AAW0461	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700573
NEW 494AAW0468 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700578 NEW 494AAW0478 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700575 NEW 494AAW0491 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700569 NEW 494AAW0493 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700582 NEW 494AAW0495 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700582 NEW 494AAW0496 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700574 NEW 494AAW0505 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700585 NEW 494AAW0506 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700584 NEW 494AAW0508 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700577 NEW 494AAW0511 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0517	NEW	494AAW0465	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700565
NEW 494AAW0478 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700575 NEW 494AAW0491 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700569 NEW 494AAW0493 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700582 NEW 494AAW0495 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700586 NEW 494AAW0506 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700584 NEW 494AAW0505 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700584 NEW 494AAW0506 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700584 NEW 494AAW0508 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700577 NEW 494AAW0511 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0517 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700579 Status Serial Number	NEW	494AAW0467	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700572
NEW 494AAW0491 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700569 NEW 494AAW0493 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700582 NEW 494AAW0495 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700586 NEW 494AAW0496 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700574 NEW 494AAW0505 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700585 NEW 494AAW0506 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700584 NEW 494AAW0508 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700577 NEW 494AAW0511 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0511 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0517 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700579 Status Serial Number	NEW	494AAW0468	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700578
NEW 494AAW0493 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700582 NEW 494AAW0495 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700586 NEW 494AAW0496 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700574 NEW 494AAW0505 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700585 NEW 494AAW0506 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700584 NEW 494AAW0508 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700577 NEW 494AAW0511 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0514 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0517 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700579 LAND MOBILE RADIO INVENTORY MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700557 Status Serial Number	NEW	494AAW0478	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700575
NEW 494AAW0495 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700586 NEW 494AAW0496 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700574 NEW 494AAW0505 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700585 NEW 494AAW0506 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700584 NEW 494AAW0508 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700577 NEW 494AAW0511 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700573 NEW 494AAW0514 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0517 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700579 LAND MOBILE RADIO INVENTORY Status Serial Number Manufacturer Model Number Model Name Equip Type Sel Call NEW 494AAW0641 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700557	NEW	494AAW0491	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700569
NEW 494AAW0496 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700574 NEW 494AAW0505 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700585 NEW 494AAW0506 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700584 NEW 494AAW0508 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700577 NEW 494AAW0511 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700583 NEW 494AAW0514 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0517 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700579 LAND MOBILE RADIO INVENTORY Status Serial Number Manufacturer Model Number Model Name Equip Type Sel Call NEW 494AAW0641 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700557 NEW 494AAW0644 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700550	NEW	494AAW0493	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700582
NEW 494AAW0505 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700585 NEW 494AAW0506 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700584 NEW 494AAW0508 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700577 NEW 494AAW0511 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700578 NEW 494AAW0514 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0517 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700579 LAND MOBILE RADIO INVENTORY MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700579 Status Serial Number Model Name Equip Type Sel Call NEW 494AAW0641 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700557 NEW 494ABU0644 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700550 NEW 494ABL0682 MOTOROLA D04QKF9PW5AN </td <td>NEW</td> <td>494AAW0495</td> <td>MOTOROLA</td> <td>D04QKF9PW5AN</td> <td>ASTROM</td> <td>RAD, MOB</td> <td>700586</td>	NEW	494AAW0495	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700586
NEW 494AAW0506 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700584 NEW 494AAW0508 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700577 NEW 494AAW0511 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700578 NEW 494AAW0514 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0517 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 LAND MOBILE RADIO INVENTORY TOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700579 Status Serial Number Montacturer Model Number Model Name Equip Type Sel Call NEW 494AAW0641 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700557 NEW 494AAW0644 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700550 NEW 494ABL0682 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700562 NEW 494ABL069	NEW	494AAW0496	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700574
NEW 494AAW0508 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700577 NEW 494AAW0511 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700583 NEW 494AAW0514 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0517 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700579 LAND MOBILE RADIO INVENTORY Serial Number Manufacturer Model Number Model Name Equip Type Sel Call NEW 494AAW0641 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700557 NEW 494AAW0644 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700550 NEW 494ABL0682 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700562 NEW 494ABL0695 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700563 NEW 494ABL0716 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700563 NEW<	NEW	494AAW0505	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700585
NEW 494AAW0511 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700583 NEW 494AAW0514 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0517 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700579 LAND MOBILE RADIO INVENTORY Setaus Serial Number Manufacturer Model Number Model Name Equip Type Sel Call NEW 494AAW0641 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700557 NEW 494AAW0644 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700550 NEW 494ABL0682 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700562 NEW 494ABL0695 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700562 NEW 494ABL0716 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700563 NEW 80TH 1 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700554 NEW 80TH 2 MOTOROLA NTN	NEW	494AAW0506	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700584
NEW 494AAW0514 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700576 NEW 494AAW0517 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700579 LAND MOBILE RADIO INVENTORY Status Serial Number Manufacturer Model Number Model Name Equip Type Sel Call NEW 494AAW0641 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700557 NEW 494AAW0644 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700550 NEW 494ABL0682 MOTOROLA D04QKH9PW5AN ASTROM RAD, MOB 700562 NEW 494ABL0695 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700563 NEW 494ABL0716 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700563 NEW 494ABL0716 MOTOROLA D04QKF9PW7AN ASTROM RAD, MOB 700554 NEW 80TH 1 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 2 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 3 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 4 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR	NEW	494AAW0508	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700577
NEW 494AAW0517 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700579 LAND MOBILE RADIO INVENTORY Status Serial Number Manufacturer Model Number Model Name Equip Type Sel Call NEW 494AAW0641 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700557 NEW 494AAW0464 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700550 NEW 494AAW0644 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700550 NEW 494ABL0682 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700562 NEW 494ABL0695 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700563 NEW 494ABL0716 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700563 NEW 494ABL0716 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700554 NEW 80TH 1 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 2 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 3 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 4 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR	NEW	494AAW0511	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700583
LAND MOBILE RADIO INVENTORYStatusSerial NumberManufacturerModel NumberModel NameEquip TypeSel CallNEW494AAW0641MOTOROLAD04QKH9PW7ANASTROMRAD, MOB700557NEW494AAW0464MOTOROLAD04QKH9PW7ANASTROMRAD, MOB700550NEW494ABL0682MOTOROLAD04QKF9PW5ANASTROMRAD, MOB700562NEW494ABL0695MOTOROLAD04QKF9PW5ANASTROMRAD, MOB700563NEW494ABL0716MOTOROLAD04QKH9PW7ANASTROMRAD, MOB700554NEW80TH 1MOTOROLANTN 1177DMULTI-UNITMULTI CHGRNEW80TH 2MOTOROLANTN 1177DMULTI-UNITMULTI CHGRNEW80TH 3MOTOROLANTN 1177DMULTI-UNITMULTI CHGRNEW80TH 4MOTOROLANTN 1177DMULTI-UNITMULTI CHGR	NEW	494AAW0514	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700576
StatusSerial NumberManufacturerModel NumberModel NameEquip TypeSel CallNEW494AAW0641MOTOROLAD04QKH9PW7ANASTROMRAD, MOB700557NEW494AAW0464MOTOROLAD04QKH9PW7ANASTROMRAD, MOB700550NEW494ABL0682MOTOROLAD04QKF9PW5ANASTROMRAD, MOB700562NEW494ABL0695MOTOROLAD04QKF9PW5ANASTROMRAD, MOB700563NEW494ABL0716MOTOROLAD04QKF9PW7ANASTROMRAD, MOB700554NEW80TH 1MOTOROLANTN 1177DMULTI-UNITMULTI CHGRNEW80TH 2MOTOROLANTN 1177DMULTI-UNITMULTI CHGRNEW80TH 3MOTOROLANTN 1177DMULTI-UNITMULTI CHGRNEW80TH 4MOTOROLANTN 1177DMULTI-UNITMULTI CHGR	NEW	494AAW0517	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700579
NEW 494AAW0641 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700557 NEW 494AAW0644 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700550 NEW 494AAW0644 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700550 NEW 494ABL0682 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700562 NEW 494ABL0695 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700563 NEW 494ABL0716 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700554 NEW 80TH 1 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 2 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 3 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 4 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR	LAND	MOBILE RADIO II	NVENTORY				
NEW 494AAW0464 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB NEW 494AAW0644 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700550 NEW 494ABL0682 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700562 NEW 494ABL0695 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700563 NEW 494ABL0716 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700554 NEW 80TH 1 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 2 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 3 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 4 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR	Status	Serial Number	Manufacturer	Model Number	Model Name	Equip Type	Sel Call
NEW 494AAW0644 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700550 NEW 494ABL0682 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700562 NEW 494ABL0695 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700563 NEW 494ABL0716 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700554 NEW 80TH 1 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 2 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 3 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 4 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR	NEW	494AAW0641	MOTOROLA	D04QKH9PW7AN	ASTROM	RAD, MOB	700557
NEW 494ABL0682 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700562 NEW 494ABL0695 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700563 NEW 494ABL0716 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700554 NEW 80TH 1 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 2 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 3 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 4 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR	NEW	494AAW0464	MOTOROLA	D04QKH9PW7AN	ASTROM	RAD, MOB	
NEW 494ABL0695 MOTOROLA D04QKF9PW5AN ASTROM RAD, MOB 700563 NEW 494ABL0716 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700554 NEW 80TH 1 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 2 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 3 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 4 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR	NEW	494AAW0644	MOTOROLA	D04QKH9PW7AN	ASTROM	RAD, MOB	700550
NEW 494ABL0716 MOTOROLA D04QKH9PW7AN ASTROM RAD, MOB 700554 NEW 80TH 1 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 2 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 3 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 4 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR	NEW	494ABL0682	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700562
NEW 80TH 1 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 2 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 3 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 4 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR	NEW	494ABL0695	MOTOROLA	D04QKF9PW5AN	ASTROM	RAD, MOB	700563
NEW 80TH 2 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 3 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 4 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR	NEW	494ABL0716	MOTOROLA	D04QKH9PW7AN	ASTROM	RAD, MOB	700554
NEW 80TH 3 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR NEW 80TH 4 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR	NEW	80TH 1	MOTOROLA	NTN 1177D	MULTI-UNIT	MULTI CHGF	₹
NEW 80TH 4 MOTOROLA NTN 1177D MULTI-UNIT MULTI CHGR							
			MOTOROLA				
NEW 404CBH0252 MOTOROLA B1822A ELITE CENTR CONT CONS				NTN 1177D			
	NEW	404CBH0252	MOTOROLA	B1822A	ELITE CENTR	CONT CONS	3